

## Various Coupon Designs

Fig 1(a). Rectangular disbondment with a holiday defect at one end




Fig. 1(b). A circular disbondment with a small gap and a crack in the middle





Fig 1©. Disbondment along overlap of a spirally wound tape coating and a holiday at one section




Fig. 2

20250725126001




Fig. 3

203060 28426001




Fig. 4a




Fig. 4b

20250724 14:25:00




Fig. 5a




Fig. 5b

208050 28426001





Figure 6. Test 1 polarization and pH data collected under a coating disbondment and adjacent exposed defect.

2080E0" 2542600T



**Figure 7. Test 2 polarization data collected at an exposed defect and under an adjacent coating disbondment.**